


		?? - 350
		?? - 400
		?? - 400 ?
?? - 500	5150...6000	
?? - 650	15000...16000	
?? - 750	20600...25800	
?? - 1000	47500...58000	

????????????? ? ?????????????????????? ?????????? ?2



????	Aw?	Aw?	?	?1	B	H	H1	h	h1	L	L1	L2	L3	L4	L5	d	n
??-2 50	150	100	285	210	260	310	160	18	-	515	400	75	183	220	280	22	4
??-3 00	175	125	350	250	300	362	190	22	-	620	475	90	215	255	300	26	4
??-3 50	200	150	400	280	330	410	212	25	-	700	550	100	238	300	345	26	6
??-4 00	250	150	500	320	380	505	265	27	-	805	640	150	286	325	375	33	6
??-5 00	300	200	640	360	440	598	315	30	-	985	785	190	340	390	445	39	6
??-6 50	400	250	780	470	560	783	355	40	95	1270	910	190	443	480	550	39	8
??-7 50	450	300	900	560	650	783	355	40	100	1455	1040	225	498	570	645	46	8
??-1 000	600	400	1200	760	860	1018	450	45	155	1905	1400	300	645	740	805	52	8